## Appendix E. Setup Photographs

## <Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E1 of E2
Report Issued Date : Feb. 25, 2019
Report Version : Rev. 01


Report No.: FR8D2708E

Report Template No.: BU5-FR15EWL AC Version 2.0


## <Radiated Emission>

## X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E2 of E2
Report Issued Date : Feb. 25, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR8D2708E