Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSC3GG Page Number : E1 of E2
Report Issued Date : Nov. 28, 2018
Report Version : Rev. 01


Report No.: FR8O1822B

Report Template No.: BU5-FR15CBT4.0 Version 2.0


<Radiated Emission>

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSC3GG Page Number : E2 of E2
Report Issued Date : Nov. 28, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 2.0

Report No.: FR8O1822B