


Report No.: FR850814B

Appendix E. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XMSE10A Page Number : E1 of E2 Report Issued Date : Jun. 20, 2018 Report Version : Rev. 01


Report Template No.:BU5-FR15CBT4.0/5.0Version 2.0



<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XMSE10A Page Number : E2 of E2
Report Issued Date : Jun. 20, 2018
Report Version : Rev. 01
Report Template No.:BU5-FR15CBT4.0/5.0Version 2.0

Report No.: FR850814B