Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E1 of E2
Report Issued Date Mar. 14, 2019
Report Version : Rev. 01

Report No.: FR911620B


Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0

<Radiated Emission> (Bluetooth v4.2/5.0 LE) X Plane (EUT slide Open)

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E2 of E2
Report Issued Date Mar. 14, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0

Report No.: FR911620B