

## Appendix E. Setup Photographs

## <Conducted Emission>

## Mode 1



Remote View



Rear View

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX:86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E1 of E2
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01


Report No.: FR8O2308D

Report Template No.: BU5-FR15EWL AC MA Version 2.0




## <Radiated Emission>

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX:86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E2 of E2
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01

Report No.: FR8O2308D

Report Template No.: BU5-FR15EWL AC MA Version 2.0