Appendix C. Setup Photographs

<Radiated Emission>

Y Plane for LTE Band 2 / 4 / 38

LF



HF




Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : C1 of C4
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01


Report No.: FG8D1803B

Z Plane for LTE Band 5

LF



HF




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : C2 of C4
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01

Report No.: FG8D1803B

X Plane for LTE Band 7

LF



HF




TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : C3 of C4
Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01


Report No.: FG8D1803B

X Plane for LTE Band 7CA

LF



HF



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : C4 of C4

Report No.: FG8D1803B

Report Issued Date : Jan. 23, 2019
Report Version : Rev. 01