

Report No.: FR8O2308C

Appendix E. Setup Photographs

<Conducted Emission>



TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E1 of E2
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 2.0




<Radiated Emission>

X Plane

LF



HF



____THE END-

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF7G Page Number : E2 of E2
Report Issued Date : Jan. 16, 2019
Report Version : Rev. 01

Report No.: FR8O2308C

Report Template No.: BU5-FR15CWL AC MA Version 2.0