

## Report No.: FR862604A

# Appendix E. Setup Photographs

# <Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E1 of E2
Report Issued Date Aug. 02, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0




Report No.: FR862604A

### <Radiated Emission>

#### **Z** Plane

LF







TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : E2 of E2
Report Issued Date Aug. 02, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0