

Report No.: FR850814E

Appendix E. Setup Photographs

<Conducted Emission>





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XMSE10A Page Number : E1 of E2
Report Issued Date : Jun. 20, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 2.0




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFZZ-XMSE10A Page Number : E2 of E2
Report Issued Date : Jun. 20, 2018
Report Version : Rev. 01

Report No.: FR850814E

Report Template No.: BU5-FR15EWLB4 AC MA Version 2.0