
## Appendix D. SAR Test Setup Photos





Report No.: FA782506

**Right Cheek** 

**Right Tilted** 





Left Cheek **Left Tilted** 

TEL: +86-512-57900158 / FAX: +86-512-57900958

Issued Date: Oct. 16, 2017 FCC ID: 2AFZZ-RMMEG7 Page D1 of D4 Form version. : 170509





Front, Test Separation 10 mm



Report No.: FA782506

Back, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



**Bottom Side, Test Separation 10 mm** 

TEL: +86-512-57900158 / FAX: +86-512-57900958

FCC ID : 2AFZZ-RMMEG7

Issued Date : Oct. 16, 2017 Form version. : 170509

Page D2 of D4






**Report No. : FA782506** 

Front, Test Separation 15 mm


Back, Test Separation 15 mm




Front, Test Separation 0 mm



Back, Test Separation 0 mm



Top Side, Test Separation 0 mm



Bottom Side, Test Separation 0 mm

TEL: +86-512-57900158 / FAX: +86-512-57900958

Issued Date: Oct. 16, 2017 FCC ID: 2AFZZ-RMMEG7 Form version. : 170509 Page D3 of D4



Report No.: FA782506

Right Side, Test Separation 0 mm

TEL: +86-512-57900158 / FAX: +86-512-57900958

Issued Date: Oct. 16, 2017 FCC ID: 2AFZZ-RMMEG7 Page D4 of D4 Form version. : 170509