
Appendix C. Setup Photographs

<Radiated Emission>

Z Plane for 27L

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6H Page Number : C1 of C4
Report Issued Date : May 23, 2018
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0


Report No.: FG820819-01B

X Plane for 22H

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6H Page Number : C2 of C4
Report Issued Date : May 23, 2018
Report Version : Rev. 01

Report No. : FG820819-01B


Report Template No.: BU5-FGLTE Version 2.0

Y Plane for 27M (LTE Band 7)

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AFZZ-RMSE6H Page Number : C3 of C4
Report Issued Date : May 23, 2018
Report Version : Rev. 01

Report No. : FG820819-01B


Report Template No.: BU5-FGLTE Version 2.0

Y Plane for 27M (LTE Band 38)

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCCID: 2AFZZ-RMSE6H Page Number : C4 of C4
Report Issued Date : May 23, 2018
Report Version : Rev. 01

Report No. : FG820819-01B

Report Template No.: BU5-FGLTE Version 2.0