
# Appendix C. Setup Photographs

## <Radiated Emission>

Z Plane for 22H / Antenna1 of 24E

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : C1 of C4 Report Issued Date: Aug. 02, 2018 Report Version : Rev. 01

Report No.: FG862604A

### Z Plane for Antenna1 of 27L

LF




HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : C2 of C4
Report Issued Date : Aug. 02, 2018
Report Version : Rev. 01

Report No.: FG862604A



#### Y Plane for Antenna2 of 27L

LF



HF




Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : C3 of C4
Report Issued Date : Aug. 02, 2018
Report Version : Rev. 01

#### X Plane for Antenna2 of 24E

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TG Page Number : C4 of C4
Report Issued Date : Aug. 02, 2018
Report Version : Rev. 01

Report No.: FG862604A