
Appendix C. Test Setup Photographs

<Radiated Emission>

Y Plane for Part 22H

LF



HF



Sporton International (KunShan) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : C1 of C2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2


Report No.: FG762302A

Z Plane for Part 24E

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFZZ-RMSG6 Page Number : C2 of C2
Report Issued Date : Jul. 12, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2

Report No.: FG762302A