Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E1 of E3
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0


Report No.: FR8D2708B

RF Test Report No.: FR8D2708B


<Radiated Emission> (Bluetooth v4.2 LE)

X Plane

LF



HF



Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E2 of E3
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0


<Radiated Emission> (Bluetooth v5.0 LE)

X Plane

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF2G Page Number : E3 of E3
Report Issued Date Feb. 25, 2019
Report Version : Rev. 01

Report No.: FR8D2708B

Report Template No.: BU5-FR15CBT4.2/5.0 Version 2.0