Appendix E. Setup Photographs

<Conducted Emission>

Mode 1



Remote View



Rear View

Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E1 of E2
Report Issued Date : Mar. 19, 2019
Report Version : Rev. 01

Report No.: FR911620E


Report Template No.: BU5-FR15EWL AC MA Version 2.0

<Radiated Emission>

LF



HF



TEL: 86-512-57900158 FAX:86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E2 of E2
Report Issued Date : Mar. 19, 2019
Report Version : Rev. 01

Report No.: FR911620E

Report Template No.: BU5-FR15EWL AC MA Version 2.0