## Appendix D. Setup Photographs

## <Conducted Emission>

## Mode 1






Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : D1 of D2
Report Issued Date Mar. 14, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0


Report No.: FR911620A

## <Radiated Emission> X Plane (EUT slide Open)

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : D2 of D2
Report Issued Date Mar. 14, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR911620A