

## Appendix E. Setup Photographs

## <Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : E1 of E2 : Jan. 23, 2019 Report Issued Date Report Version : Rev. 01

Report No.: FR8D1803B


Report Template No.: BU5-FR15CBT4.2 Version 2.0




## <Radiated Emission>

X Plane

LF



HF



——THE END—

Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-RMSF6LG Page Number : E2 of E2
Report Issued Date : Jan. 23, 2019

Report No.: FR8D1803B

Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.2 Version 2.0