
Appendix E. Setup Photographs

<Conducted Emission>

Mode 1






Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF11G Page Number : E1 of E2
Report Issued Date Jul. 08, 2019
Report Version : Rev. 01
Report Template No.: BU5-FR15CBLE Version 2.0


Report No.: FR921903-02B

<Radiated Emission> (Bluetooth v4.2/5.0 LE)





HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF11G Page Number : E2 of E2
Report Issued Date Jul. 08, 2019
Report Version : Rev. 01

Report No.: FR921903-02B

Report Template No.: BU5-FR15CBLE Version 2.0