Appendix E. Setup Photographs

<Conducted Emission>

Mode 1





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E1 of E2
Report Issued Date Mar. 12, 2019
Report Version : Rev. 01


Report No.: FR911620C


Report Template No.: BU5-FR15CWL AC MA Version 2.0

<Radiated Emission>

X Plane (EUT slide Closed)

LF





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSE5GG Page Number : E2 of E2
Report Issued Date Mar. 12, 2019
Report Version : Rev. 01

Report No.: FR911620C

Report Template No.: BU5-FR15CWL AC MA Version 2.0