

# Appendix D. Setup Photographs

## <Conducted Emission>

#### Mode 2



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : D1 of D2
Report Issued Date Apr. 04, 2018
Report Version : Rev. 01

Report No.: FR820819C


Report Template No.: BU5-FR15CWL Version 2.0




### <Radiated Emission>

#### X Plane

LF





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE6G Page Number : D2 of D2
Report Issued Date Apr. 04, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR820819C