
# Appendix A. Setup Photographs

# <AC Conducted Emission>

#### Mode 4





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMMEG7 Page Number : A1 of A4
Report Issued Date : Oct. 10, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC782506

Report No. : FC782506

#### Mode 6





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMMEG7 Page Number : A2 of A4
Report Issued Date : Oct. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


# <Radiated Emission>

# Mode 1

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMMEG7 Page Number : A3 of A4
Report Issued Date : Oct. 10, 2017
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3

Report No.: FC782506


C Test Report No. : FC782506

# Mode 5

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMMEG7 Page Number : A4 of A4
Report Issued Date : Oct. 10, 2017
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.3