

Report No.: FR8N2303D

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : D1 of D2
Report Issued Date : Jan. 17, 2019
Report Version : Rev. 01


Report Template No.: BU5-FR15CNFC Version 2.0



Report No.: FR8N2303D

<Radiated Emission>

Z plane



From 9kHz~30MHz

From 30MHz~1GHz

-THE END-

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AFZZ-XMSF1G Page Number : D2 of D2 Report Issued Date : Jan. 17, 2019 Report Version : Rev. 01

Report Template No.: BU5-FR15CNFC Version 2.0