
Appendix C. Setup Photographs

<Radiated Emission>

X Plane for Antenna1 of 22H, 27L

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TH Page Number : C1 of C4
Report Issued Date : Aug. 21, 2018
Report Version : Rev. 01
Report Template No.: BU5-FG22/24/27 Version 2.0


Report No.: FG862604-01A



Report No. : FG862604-01A

Z Plane for Antenna2 of 22H

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TH Page Number : C2 of C4
Report Issued Date : Aug. 21, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0


Report No. : FG862604-01A

X Plane for 24E

LF



HF



Sporton International (Kunshan) Inc.


TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TH Page Number : C3 of C4
Report Issued Date : Aug. 21, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0


Report No. : FG862604-01A

Y Plane for Antenna2 of 27L

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AFZZ-RMSE7TH Page Number : C4 of C4
Report Issued Date : Aug. 21, 2018
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 2.0