Department: Engineering	Page No.: 0
	DOC No./Version: N/A
	Effective Date: N/A

SPEAC™ Detection Device Internal Photographs

ı		
Authored By:	Signature:	Date:
N/A		
Reviewed By:	Signature:	Date:
N/A		
Reviewed By:	Signature:	Date:
•		
N/A		
Approved By:	Signature:	Date:
	-	
N/A		

	Revision History		
Version No.	Effective Date	Author	Description
0.1		James Fox	Initial Release

Department: Engineering	Page No.: 1
	DOC No./Version: N/A
	Effective Date: N/A

1 DD Interior Front and Rear




Figure 1

Department: Engineering	Page No.: 2
	DOC No./Version: N/A
	Effective Date: N/A

2 DD Subassemblies




Figure 2

Department: Engineering	Page No.: 3
	DOC No./Version: N/A
	Effective Date: N/A

3 Rear Case Assembly



Figure 3

Department: Engineering	Page No.: 4
	DOC No./Version: N/A
	Effective Date: N/A

4 Front Case Subassemblies



Figure 4

Department: Engineering	Page No.: 5
	DOC No./Version: N/A
	Effective Date: N/A

5 Board Stack Assembly




Figure 5

Department: Engineering	Page No.: 6
	DOC No./Version: N/A
	Effective Date: N/A




Figure 6

Department: Engineering	Page No.: 7
	DOC No./Version: N/A
	Effective Date: N/A

6 EMG PCB Assembly




Figure 7

Department: Engineering	Page No.: 8
	DOC No./Version: N/A
	Effective Date: N/A

7 MCU PCB Assembly




Figure 8

Department: Engineering	Page No.: 9
	DOC No./Version: N/A
	Effective Date: N/A

8 Battery Assembly



Figure 9

Department: Engineering	Page No.: 10
	DOC No./Version: N/A
	Effective Date: N/A

9 Redpine Module Modifications

9.1 **RS9110-N-11-22-05 Modifications**




Figure 10

9.1.1 Instructions

- Remove component at location shown in Error! Reference source not found..
- Add 5.6nH inductor (Johanson Technology PN = L-05B5N6SV6) at location shown in **Error! Reference source not found.**