

Date: 28/2/2016

Attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

To Whom It May Concern:

The Pointer Telocation, Multi-Sensing Device, Model MultiSense TH, MultiSense, FCC ID: 2AG69MS, and label are so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)

"This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

OR ROGOV 17-03-2016 VP R&D

Sincerely,

Signature / Igor Rogov

VP R&D

Pointer Telocation Inc.