



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration




Report No.: FR5D0109AF

: A1 of A6

: Rev. 01

FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version



FCC Test Report Report No.: FR5D0109AF



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A6

Report Version

: Rev. 01

Report No.: FR5D0109AF




FCC Test Report


Report No.: FR5D0109AF

For radiated emissions 30MHz~1GHz

Mode 1



FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR5D0109AF

Mode 2



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6

Report Version

: Rev. 01




FCC Test Report

Report No.: FR5D0109AF


: A6 of A6

: Rev. 01

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No.
TEL: 886-3-327-3456 Report Version