




Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Report No.: FR5D0109AD

FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01



FCC Test Report Report No.: FR5D0109AD



SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01






1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456

FAX: 886-3-327-0973

Page No. : A3 of A6

Report Version

: Rev. 01

Report No.: FR5D0109AD




FCC Test Report


Report No.: FR5D0109AD

For radiated emissions 30MHz~1GHz

Mode 1



FRONT VIEW




REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A4 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01





Mode 2



Report No.: FR5D0109AD

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6 : Rev. 01


Report Version




FCC Test Report

Report No.: FR5D0109AD

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A6 of A6
TEL: 886-3-327-3456 Report Version : Rev. 01