


# Appendix E. Setup Photographs

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E1 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01B





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E2 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01B




### <Radiated Emission>

### Z Plane with Tx mode

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E3 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01B




### Z Plane with RJ-45 Cable mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E4 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01B