


Appendix C. Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : C1 of C4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01A







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : C2 of C4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04




<Radiated Emission>

Z Plane with Tx mode

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : C3 of C4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01A




Z Plane with RJ-45 Cable mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : C4 of C4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01A