


Appendix E. Setup Photographs

<Conducted Emission>

Mode 1




Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E1 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04

Report No.: FR6O0801-01C







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E2 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04




<Radiated Emission>

Z Plane for TX Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E3 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04


Report No.: FR6O0801-01C




Report No.: FR6O0801-01C

Z Plane for RJ-45 Cable Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E4 of E4
Report Issued Date : Nov. 17, 2016
Report Version : Rev. 04