

## Report No. : FR6O0801-01E

# Appendix E. Setup Photographs

### <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E1 of E4
Report Issued Date : Nov. 14, 2016
Report Version : Rev. 02







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E2 of E4
Report Issued Date : Nov. 14, 2016
Report Version : Rev. 02



#### Report No.: FR6O0801-01E


#### <Radiated Emission>

#### **Z Plane with Tx Mode**

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E3 of E4
Report Issued Date : Nov. 14, 2016
Report Version : Rev. 02




Report No.: FR6O0801-01E

#### Z Plane with RJ-45 Cable Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AG7G-A1A Page Number : E4 of E4
Report Issued Date : Nov. 14, 2016
Report Version : Rev. 02