
Appendix E. Setup Photographs

<Conducted Emission>

Mode 2





Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AG7G-A2A Page Number : E1 of E3
Report Issued Date : Oct. 30, 2018
Report Version : Rev. 01


Report No.: FR860502B

Report Template No.: BU5-FR15CWL AC MA Version 2.0


<Radiated Emission>

Y Plane for Ant. 1

LF



HF



Sporton International (Kunshan) Inc.


TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AG7G-A2A Page Number : E2 of E3
Report Issued Date : Oct. 30, 2018
Report Version : Rev. 01

Report No.: FR860502B

Report Template No.: BU5-FR15CWL AC MA Version 2.0

Z Plane for Ant. 1+2

LF



HF



Sporton International (Kunshan) Inc.

TEL: 86-512-57900158 FAX: 86-512-57900958 FCC ID: 2AG7G-A2A Page Number : E3 of E3
Report Issued Date : Oct. 30, 2018
Report Version : Rev. 01

Report No.: FR860502B

Report Template No.: BU5-FR15CWL AC MA Version 2.0