

1. Photographs of AC Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F1 of F6 Report Version : Rev. 01

Project No. : 681022





Side view

SPORTON INTERNATIONAL INC.

Page No.

Page No.

Page No.

 TEL: 886-3-327-3456
 Report Version
 : Rev. 01

 FAX: 886-3-327-0973
 Project No.
 : 681022


: F2 of F6



2. Photographs of RF Conducted Emissions Test Configuration



Front view



EUT close up photo


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F3 of F6 Report Version : Rev. 01


Project No. : 681022



3. Photographs of Radiated Emissions Test Configuration For Radiated Emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version


: F4 of F6 : Rev. 01

Project No.


: 681022



For Radiated Emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. :

Project No.

: F5 of F6 : Rev. 01 : 681022



For Radiated Emissions Above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version

: F6 of F6 : Rev. 01

Project No.

: 681022