

Test Photos Appendix F

1. Photographs of AC Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F1 of F6

Report Version : Rev. 01 Project No. : 681022



Test Photos Appendix F



Side view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F2 of F6 Report Version

Project No.

: Rev. 01 : 681022



Test Photos Appendix F

2. Photographs of RF Conducted Emissions Test Configuration



Front view



EUT close up photo

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F3 of F6 Report Version : Rev. 01

Project No. : 681022




Test Photos Appendix F

3. Photographs of Radiated Emissions Test Configuration For Radiated Emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version


Project No.

: F4 of F6 : Rev. 01 : 681022




Test Photos Appendix F

For Radiated Emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F5 of F6 Report Version

: Rev. 01 Project No. : 681022




Test Photos Appendix F

For Radiated Emissions Above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. Report Version

: F6 of F6 : Rev. 01 : 681022

Project No. :