

## Appendix C. Setup Photographs

## <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AGDE-COUPLER Page Number : C1 of C2
Report Issued Date : Nov. 06, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0

Report No.: FR5O0126




Report No.: FR5O0126


## <Radiated Emission>

## X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AGDE-COUPLER Page Number : C2 of C2
Report Issued Date : Nov. 06, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0