



151710_15.jpg: EUT - front view

 Examiner:
 Paul NEUFELD
 Report Number:
 F151710E2

 Date of issue:
 20.04.2016
 Order Number:
 15-111710
 page 1 of 6





151710_16.jpg: EUT - rear view

 Examiner:
 Paul NEUFELD
 Report Number:
 F151710E2

 Date of issue:
 20.04.2016
 Order Number:
 15-111710
 page 2 of 6





151710_17.jpg: EUT - left hand side view

 Examiner:
 Paul NEUFELD
 Report Number:
 F151710E2

 Date of issue:
 20.04.2016
 Order Number:
 15-111710
 page 3 of 6





151710_18.jpg: EUT - right hand side view

 Examiner:
 Paul NEUFELD
 Report Number:
 F151710E2

 Date of issue:
 20.04.2016
 Order Number:
 15-111710
 page 4 of 6






151710_19.jpg: EUT - label view

 Examiner:
 Paul NEUFELD
 Report Number:
 F151710E2

 Date of issue:
 20.04.2016
 Order Number:
 15-111710
 page 5 of 6





151710_20.jpg: EUT – bottom view

 Examiner:
 Paul NEUFELD
 Report Number:
 F151710E2

 Date of issue:
 20.04.2016
 Order Number:
 15-111710
 page 6 of 6