


INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)





INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)



FCC ID: 2AGFQ4ARI0102



INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)



INTERTEK TESTING SERVICE

Report No.: 15100841HKG-001

Equipment Photographs

Model: 4ARI0102

(Internal)

