RE: Triax Technologies FCC ID: 2AGHICP01 IC: 21358-CP01 ATCB023242

12/20 ACB – Please confirm all transmitters(*including Cellular*) were transmitting during the EMC testing of the DTS & DSS transmitter per FCC Part 2.947(f) and update reports accordingly – my apologies I missed this during my initial review.

Laird 2/14 –The device was tested in a simultaneous transmission mode and was found to be compliant