

RFID Antenna Located inside here

Figure 1: Photo of O-PEL unit (Front Side)

Report Number: 31563434.001

EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015




Figure 2: RFID Board location

RFID Board

Report Number: 31563434.001 EUT: Opel Surgical System Model: O-PEL Page 2 of 8

EMC / Rev 12/22/2015




Figure 3: RFID Antenna location

Report Number: 31563434.001 EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015

Page 4 of 8




Figure 4: Internal Photo of RFID - PCB Board

Report Number: 31563434.001

EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015




Figure 5: Internal Photo of RFID - PCB Board Close up View

Report Number: 31563434.001

EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015




Figure 6: Internal Photo of RFID - PCB Board backside

Report Number: 31563434.001 EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015



Figure 7: Internal Photo of RFID - probe with tag

Passive Tag

Tag shown outside is placed inside probe connector

Report Number: 31563434.001

EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015



Figure 8: RFID -Tag (Enlarged) this tag is built into Probe connector

Report Number: 31563434.001

EUT: Opel Surgical System Model: O-PEL

EMC / Rev 12/22/2015