



Report No.:FZ831528-02

Appendix A. Test Photos
1. Photographs of Dynamic Frequency Selection Test Configuration



Front View

SPORTON INTERNATIONAL INC. Page No. : A1 of A1 TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973