



FCC Test Report Report No.: FR5D2513

Appendix A. Test Photos 1. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A6 Report Version : Rev. 01




FCC Test Report


Report No.: FR5D2513

For radiated emissions 30MHz~1GHz

Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A2 of A6 : Rev. 01


Report Version






Report No.: FR5D2513

Mode 2



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A6

Report Version : Rev. 01




FCC Test Report


Report No. : FR5D2513

For radiated emissions above 1GHz

Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.
TEL: 886-3-327-3456

FAX: 886-3-327-0973


Page No. : A4 of A6 Report Version : Rev. 01





Report No.: FR5D2513

Mode 2



Front view




Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6

Report Version

: Rev. 01







EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6

Report Version : I

: Rev. 01

Report No.: FR5D2513