

Internal Photos Antenna 1 and 2







February 24, 2015

Re: Internal Photos of the 940-0132 Module

FCC ID: 2AGQP-F5500

IC: <u>20936-F5500</u>

To Whom It May Concern,

Rain Bird Corporation does not have internal photos of the 940-0132 Module, as the modules are manufactured using a SIP (System In Package) process. This process results in the final modules being encapsulated in the packaging material during time of manufacture. Based on this we are unable to provide pictures of the module without the cover.

Sincerely,

ANDERSON MICU


Rain Bird Corporation 9491 Ridgehaven Court


San Diego, CA 92111

(858) 268-2638

amicu@rainbird.com


EXTERNAL PHOTOS	
Company Name	Rain Bird Corporation
FCC ID #	2AGQP-F5500
IC#	20936-F5500





EXTERNAL PHOTOS	
Company Name	Rain Bird Corporation
FCC ID #	2AGQP-F5500
IC#	20936-F5500







Page **2** of **2**