
## 3. Internal Photograph of EUT

Brand Name: 37Degree / Model Name: B3702


Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 15 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01




Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 16 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01



Report No.: EP642809




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702

: 17 of 31 Page Number Report Issued Date : Jul. 13, 2016 Report Version : Rev. 01



Report No.: EP642809




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702

Page Number : 18 of 31 Report Issued Date : Jul. 13, 2016 Report Version : Rev. 01



Report No.: EP642809




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 19 of 31
Report Issued Date : Jul. 13, 2016

Report Version : Rev. 01



Report No.: EP642809




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702

: 20 of 31 Page Number Report Issued Date : Jul. 13, 2016 Report Version : Rev. 01



Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 21 of 31
Report Issued Date : Jul. 13, 2016

Report Version : Rev. 01






SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 22 of 31
Report Issued Date : Jul. 13, 2016

Report Version : Rev. 01



Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702

Page Number : 23 of 31 Report Issued Date : Jul. 13, 2016 Report Version : Rev. 01

Report No.: EP642809




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 24 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01

Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 25 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01


Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 26 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01



Report No.: EP642809




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702

Page Number : 27 of 31 Report Issued Date : Jul. 13, 2016 Report Version : Rev. 01




Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702


: 28 of 31 Page Number Report Issued Date : Jul. 13, 2016 Report Version : Rev. 01

Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 29 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01


Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 30 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01



Report No.: EP642809



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-B3702 Page Number : 31 of 31
Report Issued Date : Jul. 13, 2016
Report Version : Rev. 01