
2. Internal Photograph of EUT

Brand Name: 37 Degree; Model Name: 37 Light

Report No.: EP580711



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 13 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L

Page Number : 14 of 26 Report Issued Date : Dec. 17, 2015


Report Version : Rev. 01

Brand Name: 37 Degree; Model Name: 37 Light



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 15 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01

Report No.: EP580711




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 16 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01

Brand Name: 37 Degree; Model Name: 37 Light



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 17 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01






Report No.: EP580711

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L


Page Number : 18 of 26 Report Issued Date : Dec. 17, 2015 Report Version : Rev. 01



Brand Name: 37 Degree; Model Name: 37 Light

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 19 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01



Brand Name: 37 Degree; Model Name: 37 Light

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 20 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01



Brand Name: 37 Degree; Model Name: 37 Light

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 21 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01




Brand Name: 37 Degree; Model Name: 37 Light

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 22 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01




Report No.: EP580711



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L


Page Number : 23 of 26 Report Issued Date : Dec. 17, 2015 Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 24 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01

Report No.: EP580711



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 25 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGVW-HM1L Page Number : 26 of 26
Report Issued Date : Dec. 17, 2015
Report Version : Rev. 01