Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : A1 of A2
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3


Report No. : FC690802

C Test Report No.: FC690802

<Radiated Emission>

Mode 1

LF





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : A2 of A2
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01
Report Template No.: BU5-FD15B Version 1.3