

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : B1 of B2
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR690802A







<Radiated Emission>

X Plane

LF



 ${\sf HF}$



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : B2 of B2
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR690802A