

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : D1 of D2
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1


Report No.: FR690802B




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AGZ3S00211 Page Number : D2 of D2
Report Issued Date : Jan. 25, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR690802B