

Appendix D. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AH25V1 Page Number : D1 of D2
Report Issued Date : Jun. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3


Report No.: FR630406B

FCC RF Test Report


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AH25V1 Page Number : D2 of D2
Report Issued Date : Jun. 27, 2016
Report Version : Rev. 01

Report No.: FR630406B

Report Template No.: BU5-FR15CBT4.0 Version 1.3