



**Appendix A. Test Photos** 

1. Photographs of Conducted Emissions Test Configuration



Report No.: FR620221AC

**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No.: FR620221AC

**SIDE VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01






## 1 Photographs of Radiated Emissions Test Configuration

For radiated emissions 9kHz~30MHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A5

Report Version

: Rev. 01


Report No. : FR620221AC




# FCC Test Report

Report No.: FR620221AC

#### For radiated emissions 30MHz~1GHz



**FRONT VIEW** 



**REAR VIEW** 


SPORTON INTERNATIONAL INC. Page No. : A4 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01




### FCC Test Report

Report No.: FR620221AC

#### For radiated emissions above 1GHz



**FRONT VIEW** 



**REAR VIEW** 

SPORTON INTERNATIONAL INC. Page No. : A5 of A5 TEL: 886-3-327-3456 Report Version : Rev. 01