




**Appendix A. Test Photos** 

1. Photographs of Conducted Emissions Test Configuration

Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A7

Report Version : Re


: Rev. 01

Report No.: FR633007AL





Report No. : FR633007AL



Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973





Report No.: FR633007AL

Mode 2



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A7
Report Version : Rev. 01





Report No. : FR633007AL



Side view

SPORTON INTERNATIONAL INC. Page No. : A4 of A7
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973




FCC Test Report Report No.: FR633007AL

# 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A7

Report Version

: Rev. 01




## FCC Test Report


Report No.: FR633007AL

### For radiated emissions 30MHz~1GHz

Mode 1



#### Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A7

Report Version : Rev. 01






Report No.: FR633007AL



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A7 of A7

Report Version


: Rev. 01



## FCC Test Report

Report No.: FR633007AL

#### For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A8 of A7

Report Version

: Rev. 01





Report No.: FR633007AL



EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A9 of A7
Report Version : Rev. 01